


DPX™ AUXILIARY INPUT CONVERTER

APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.
 ***FOR SATELLITE RADIO INTEGRATION, SEE BACK PAGE

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
ACURA				
All Models	1992-2001	HON-AUX	8-Pin DIN in trunk	
Note 1: Not compatible with: "RL" with Navigation, "NSX", "SLX" - 1996 and Up, "3.2TL" - 1999-2003, "MDX" - 2001-2003				
AUDI				
All Models	1998-2002	AUD-AUX	13-Pin DIN-Cable in rear, drivers side	
All Models	1998-2004	VWR-AUX	8-Pin data port at headunit	
Models equipped with the "Symphony II" (6-disc in-dash) headunit will require PIE Part # AA3-HAR to gain access to the external CD Changer port (8-pin data port).				
BMW				
All Models	1996-2003	BMW/PC-SON	3 & 6-Pin connector in rear driver side	Not compatible with 7-Series.
Note: BMW/PC-SON can be used as an auxiliary input or CD-Changer interface.				
BUICK				
Century	1997-2003	GM10-AUX	Cable in trunk	
Le Sabre	1995-1999	GM10-AUX	Cable in trunk	Not compatible with 2000-2004 Le Sabre.
Park Ave	1995-2003	GM10-AUX	Cable in trunk	
Regal	1995-2003	GM10-AUX	Cable in trunk	Not compatible with 2004 Regal.
Riviera	1996-1999	GM10-AUX	Cable in trunk	
Roadmaster	1995-1996	GM10-AUX	Cable in trunk	
Skylark	1996-1998	GM10-AUX	Cable in trunk	
Note: All vehicles listed above require GM factory CD data cable, Part # 12344003, if not pre-wired.				
CADILLAC				
Catera *	1997-1999	GM10-AUX	Trunk	* Catera requires Cadillac factory CD data cable Part # 12484910 if not pre-wired.
DeVille	1995-1999	GM10-AUX	Trunk	Not compatible with 2000-2004 DeVille.
Eldorado	1995-2002	GM10-AUX	Trunk	Not compatible with 2003 El Dorado.
Escalade	1999-2002	GM9-AUX	Headunit	Not compatible with 2003-2004 Escalade.
Escalade	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
EXT	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Seville	1995-2001	GM10-AUX	Center Console	Not compatible with 2002-2004 Seville.
Note 1: Not compatible with vehicles equipped with in-dash 6-disc slave unit.				
Note 2: GM radios 2000 and earlier are not capable of controlling two units; therefore, these radios will need to have the slave unit disconnected.				
CHEVROLET				
Astro Van	1996-2004	GM9-AUX	Headunit	
Avalanche	2002	GM9-AUX	Headunit	Not compatible with 2003-2004 Avalanche.
Avalanche	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Blazer	1998-2002	GM9-AUX	Headunit	Not compatible with 2003-2004 Blazer.
Blazer	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Camaro *	1997-2002	GM9-AUX	Headunit	* Radio must be AM/FM/Cassette with 'TAPE/AUX' button.
Cavalier	1996-1999	GM9-AUX	Headunit	Not compatible with 2000-2004 Cavalier
Cavalier	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Corvette	1997-2004	GM10-AUX	Trunk/Hatch	Use with PIE Part # COR-HAR if not pre-wired.
Impala	1995-1997	GM9-AUX	Headunit	Not compatible with 2000-2004 Impala
Impala	2002-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Lumina	1996-1999	GM9-AUX	Headunit	Not compatible with 2000-2004 Lumina
Lumina	2000-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Malibu *	1997-2000	GM9-AUX	Headunit	Not compatible with 2001-2004 Malibu.
Malibu	2001-2003	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Monte Carlo	1996-1999	GM9-AUX	Headunit	Not compatible with 2000-2004 Monte Carlo
Monte Carlo	2002-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
C/K Truck	1995-2002	GM9-AUX	Headunit	Not compatible with 2003-2004 C/K Truck.
C/K Truck	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
S10 Truck	1998-2002	GM9-AUX	Headunit	Not compatible with 2003-2004 S10.
S10 Truck	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Silverado	1996-2002	GM9-AUX	Headunit	Not compatible with 2003-2004 Silverado.
Silverado	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.




DPX™ AUXILIARY INPUT CONVERTER

APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.
 ***FOR SATELLITE RADIO INTEGRATION, SEE BACK PAGE

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES	
CHEVROLET-CONT					
Suburban	1995-2002	GM9-AUX	Headunit	Not compatible with 2003-2004 Suburban. Must have XM-Satellite/RDS ready headunit. Not compatible with 2003-2004 Tahoe. Must have XM-Satellite/RDS ready headunit. Must have XM-Satellite/RDS ready headunit. Not compatible with 2000-2004 Venture Must have XM-Satellite/RDS ready headunit.	
Suburban	2003-2004	GM12-AUX	12-Pin connector at headunit		
Tahoe	1995-2002	GM9-AUX	Headunit		
Tahoe	2003-2004	GM12-AUX	12-Pin connector at headunit		
TrailBlazer	2002-2004	GM12-AUX	12-Pin connector at headunit		
Venture	1997-1999	GM9-AUX	Headunit		
Venture	2003-2004	GM12-AUX	12-Pin connector at headunit		
<p>Note 1: 1995 -1999 AM/FM/CD radios are not CD changer capable; 2000-2001 model AM/FM/CD radios ARE CD changer capable. Note 2: Not compatible with vehicles equipped with in-dash 6-disc slave units. Note 3: GM radios 2000 and earlier are not capable of controlling two units; therefore, these radios will need to have the slave unit disconnected.</p>					
CHRYSLER					
300M	1999-2001	CHRY98-AUX	Headunit		
300M	2002-2003	CHRY02-AUX	10-Pin connector at headunit		
Concorde	1998-2001	CHRY98-AUX	Headunit		
Concorde	2002-2004	CHRY02-AUX	10-Pin connector at headunit		
LHS	1999-2001	CHRY98-AUX	Headunit		
LHS	2002-2004	CHRY02-AUX	10-Pin connector at headunit		
Pacifica	2003-2004	CHRY02-AUX	10-Pin connector at headunit		
PT Cruiser	2001	CHRY98-AUX	Headunit		
PT Cruiser	2002-2004	CHRY02-AUX	10-Pin connector at headunit		
Sebring	2001	CHRY98-AUX	Headunit		
Sebring	2002-2004	CHRY02-AUX	10-Pin connector at headunit		
Town & Country	2001	CHRY98-AUX	Headunit		
Town & Country	2002-2004	CHRY02-AUX	10-Pin connector at headunit		
Voyager	2001	CHRY98-AUX	Headunit		
Voyager	2002-2004	CHRY02-AUX	10-Pin connector at headunit		
<p>Note 1: CHRY98-AUX - Must be 'Rounded Face' radio with 'CD-C' button. Note 2: CHRY02-AUX – Radio must be CD changer controller. Note 3: Not compatible with "RBQ" (6-disc in-dash) radio or Chrysler Crossfire.</p>					
CHRYSLER					
All Models	1995-2000	CHRY-AUX	Headunit		
<p>Note: Radio must be one of the following CD changer controller headunits:</p> <ul style="list-style-type: none"> • 5-preset radio with 5-band EQ, "DISC ^" and "DISC v" on presets 1 and 5, and "MODE" button • 6-preset radio with Bass and Treble slider controls, "DIRECT DISC SELECT 1-6" printed above radio presets, and "MODE/EJECT" button 					
DODGE					
Caravan	2001	CHRY98-AUX	Headunit		
Caravan	2002-2004	CHRY02-AUX	10-Pin connector at headunit		
Dakota	2001	CHRY98-AUX	Headunit		
Dakota	2002-2004	CHRY02-AUX	10-Pin connector at headunit		
Durango	2001	CHRY98-AUX	Headunit		
Durango	2002-2003	CHRY02-AUX	10-Pin connector at headunit		
Intrepid	1998-2001	CHRY98-AUX	Headunit		
Intrepid	2002-2004	CHRY02-AUX	10-Pin connector at headunit		
Neon	2000-2001	CHRY98-AUX	Headunit		
Neon	2002-2004	CHRY02-AUX	10-Pin connector at headunit		
Stratus	2001	CHRY98-AUX	Headunit		
Ram 1500	2002-2004	CHRY02-AUX	10-Pin connector at headunit		
<p>Note 1: CHRY98-AUX - Must be 'Rounded Face' radio with 'CD-C' button. Note 2: CHRY02-AUX – Radio must be CD changer controller. Note 3: Not compatible with "RBQ" (6-disc in-dash) radio.</p>					
DODGE					
All Models	1995-2000	CHRY-AUX	Headunit		
<p>Note: Radio must be one of the following CD changer controller headunits:</p> <ul style="list-style-type: none"> • 5-preset radio with 5-band EQ, "DISC ^" and "DISC v" on presets 1 and 5, and "MODE" button • 6-preset radio with Bass and Treble slider controls, "DIRECT DISC SELECT 1-6" printed above radio presets, and "MODE/EJECT" button 					



DPX™ AUXILIARY INPUT CONVERTER

APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.
 ***FOR SATELLITE RADIO INTEGRATION, SEE BACK PAGE

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
EAGLE				
All Models 1995-1998 CHRY-AUX Headunit				
Note: Radio must be one of the following CD changer controller headunits:				
<ul style="list-style-type: none"> • 5-preset radio with 5-band EQ, "DISC ^" and "DISC v" on presets 1 and 5, and "MODE" button • 6-preset radio with Bass and Treble slider controls, "DIRECT DISC SELECT 1-6" printed above radio presets, and "MODE/EJECT" button 				
FORD				
Crown Victoria	1995-1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165 - Premium Audio System
Crown Victoria	1995-1997	FRDR-AUX	RCU in trunk	Radio Series 852 - JBL or LUX Audio System
Crown Victoria	1998-2002	FRDN-AUX	20-Pin connector at headunit	Radio Series 870 - Use FRDW-AUX if pre-wired
Crown Victoria	2003-2004	FRD03-AUX	16 & 24-Pin connectors at H/U	Use FRDW-AUX if pre-wired
Escape	2001-2003	RDN-AUX	20-Pin connector at headunit	Radio Series 868
Econoline	1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165
Econoline	1998-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 868, 870 or 815
Escort	1997-2003	FRDW-AUX	12-Pin data cable in trunk/rear	Radio Series 858 (Oval)-Use FRDF-AUX at H/U if not pre-wired
Excursion	2000-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 868
Expedition	1997-1998	FRDF-AUX	16-Pin connector at headunit	Radio Series 165
Expedition	1999-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 870
Explorer	1995-1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165 - Premium Audio System
Explorer	1995-1997	FRDR-AUX	RCU rear passenger side panel	Radio Series 852 - JBL or LUX Audio System
Explorer	1998-2004	FRDN-AUX	20-Pin connector at headunit	Radio Series 868
F-150 Pick Up	1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165- Not compatible with the new 2004 F-150.
F-Series Pick Up	1998-2004	FRDN-AUX	20-Pin connector at headunit	Radio Series 868
Focus	2000-2003	FRDC-AUX	12-Pin connector at headunit	Radio Series 815 or 876-Not compatible w/ Blaupunkt H/U.
HN80 Heavy Duty	1996-1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165
Mustang	2001-2004	FRDN-AUX	20-Pin connector at headunit	Radio Series 815 & 868
Ranger	1995-1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165
Ranger	1998-2004	FRDN-AUX	20-Pin connector at headunit	Radio Series 868
Sport Trac	2000-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 815
Taurus	1996-2004	FRDR-AUX	RCU in Trunk or Rear	Radio Series 858 (Oval/Trapezoidal)
Thunderbird	2002-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 132 or 868
Windstar	1999-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 815
NOTE: Not compatible with 2003 models equipped with 6-disc in-dash headunit or factory navigation system.				
GMC				
Jimmy	1998-2002	GM9-AUX	Headunit	
Envoy	1999-2001	GM9-AUX	Headunit	Not compatible with 2002-2004 Envoy.
Envoy	2002-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Sonoma	1998-2002	GM9-AUX	Headunit	Not compatible with 2003-2004 Sonoma.
Sonoma	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Safari	1996-2004	GM9-AUX	Headunit	
Sierra	1995-2002	GM9-AUX	Headunit	Not compatible with 2003-2004 Sierra.
Sierra/Denali	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Suburban	1995-2002	GM9-AUX	Headunit	Not compatible with 2003 Suburban.
Yukon	1995-2002	GM9-AUX	Headunit	Not compatible with 2003-2004 Yukon.
Yukon	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Yukon Denali	1999-2002	GM9-AUX	Headunit	Not compatible with 2003-2004 Yukon Denali.
Yukon Denali	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Yukon XL	2001-2002	GM9-AUX	Headunit	Not compatible with 2003-2004 Yukon XL.
Yukon XL	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Note 1: 1995-1999 AM/FM/CD radios are not CD changer capable; 2000-2001 model AM/FM/CD radios ARE CD changer capable.				
Note 2: Not compatible with vehicles equipped with in-dash 6-disc slave units.				
Note 3: GM radios 2000 and earlier are not capable of controlling two units; therefore, these radios will need to have the slave unit disconnected.				
HONDA				
Accord	2003-2004	HON03/PC-SON	14-Pin connector at headunit	
Element	2003-2004	HON03/PC-SON	14-Pin connector at headunit	
S2000	2004	HON03/PC-SON	14-Pin connector at headunit	
All Models *	1998-2004	HON-AUX	14-Pin data port at headunit	
All Models	1992-1998	HON-AUX	8-Pin DIN at headunit	
Note 1: Not compatible with 1995-Up Passport.				
Note 2: The HON03/PC-SON can be used as a CD-Changer or Auxiliary Input interface.				
Note 3: * indicates part is not compatible with 2003-2004 Accord, Element and 2004 S2000.				




DPX™ AUXILIARY INPUT CONVERTER

APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.
 ***FOR SATELLITE RADIO INTEGRATION, SEE BACK PAGE

MAKE/MODEL	YEAR(S)	PIE PART #	LOCATION	NOTES
<u>HUMMER</u>				
H2	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM/Satellite/RDS ready headunit.
<u>JAGUAR</u>				
S Type	2000-2002	JAGW-AUX	12-Pin data cable in trunk	Not compatible with 2003-2004 Jaguar S-Type.
S Type	2000-2002	JAG-AUX	12-Pin data port at headunit	Not compatible with 2003-2004 Jaguar S-Type.
<u>JEEP</u>				
Grand Cherokee	1999-2001	CHRY98-AUX	Headunit	
Grand Cherokee	2002-2004	CHRY02-AUX	10-Pin connector at headunit	
Liberty	2002-2004	CHRY02-AUX	10-Pin connector at headunit	
Note 1: CHRY98-AUX - Must be 'Rounded Face' radio with 'CD-C' button. Note 2: CHRY02-AUX – Radio must be CD changer controller. Note 3: Not compatible with "RBQ" (6-disc in-dash) radio.				
<u>JEEP</u>				
All Models	1996-1998	CHRY-AUX	Headunit	
Note: Radio must be CD changer controller with "MODE" button.				
<u>LANDROVER</u>				
All Models	1998-2002	LND/PC-SON	10-Pin under front passenger seat	
Note: LND/PC-SON can be used as a CD-Changer or Auxiliary Input interface.				
<u>LINCOLN</u>				
Aviator	2002-2003	FRDN-AUX	20-Pin connector at headunit	Use FRDW-AUX if pre-wired.
Continental	1995-1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165 – Premium Audio System
Continental	1995-1997	FRDR-AUX	RCU in Trunk	Radio Series 852 - JBL or LUX Audio System
Continental	1998-2002	FRDN-AUX	20-Pin connector at headunit	Radio Series 870 – Use FRDW-AUX if pre-wired
Continental	2003-2004	FRD03-AUX	16 & 24-Pin connectors at H/U	Use FRDW-AUX if pre-wired.
LS	2000-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 815 or 870
Mark VIII	1995-1998	FRDF-AUX	16-Pin connector at headunit	Radio Series 165
Navigator	1997-1998	FRDF-AUX	16-Pin connector at headunit	Radio Series 165
Navigator	1999-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 870
Town Car	1995-1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165 – Premium Audio System
Town Car	1995-1997	FRDR-AUX	RCU in Trunk	Radio Series 852 - JBL or LUX Audio System
Town Car	1998-2002	FRDW-AUX	12-Pin data cable in trunk/center console.	Radio Series 870 – Use FRDN-AUX at headunit if not pre-wired. Not compatible with 2003 Town Car.
Town Car	2003-2004	FRD03-AUX	16 & 24-Pin connectors at H/U	Use FRDW-AUX if pre-wired.
NOTE: Not compatible with 2003 models equipped with 6-disc in-dash headunit or factory navigation system.				
<u>MAZDA</u>				
B Series Truck	1995-1997	FRDF-AUX	16-Pin connector at headunit	Must be CD changer controller headunit
B Series Truck	1998-2001	FRDN-AUX	20-Pin connector at headunit	Must be CD changer controller headunit
Tribute	2001-2002	FRDN-AUX	20-Pin connector at headunit	Must be CD changer controller headunit
<u>MERCURY</u>				
Cougar	1999-2002	FRDC-AUX	12-Pin connector at headunit	Radio Series 815 or 876 -
Grand Marquis	1995-1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165 – Premium Audio System
Grand Marquis	1995-1997	FRDR-AUX	RCU in Trunk	Radio Series 852 - JBL or LUX Audio System
Grand Marquis	1998-2002	FRDN-AUX	20-Pin connector at headunit	Radio Series 870 - Use FRDW-AUX if pre-wired
Grand Marquis	2003-2004	FRD03-AUX	16 & 24-Pin connectors at H/U	Use FRDW-AUX if pre-wired.
Marauder	2003-2004	FRD03-AUX	16 & 24-Pin connectors at H/U	Use FRDW-AUX if pre-wired.
Mountaineer	1997	FRDR-AUX	RCU in rear passenger panel	Radio Series 852 - JBL or LUX Audio System
Mountaineer	1997	FRDF-AUX	16-Pin connector at headunit	Radio Series 165 – Premium Audio System
Mountaineer	1998-2003	FRDN-AUX	20-Pin connector at headunit	Radio Series 868
Sable	1996-2004	FRDR-AUX	RCU in Trunk or Rear	Radio Series 858(Oval/Trapezoidal)
Tracer	1997-2002	FRDW-AUX	12-Pin data cable in trunk/rear	Radio Series 858(Oval)-Use FRDF-AUX at H/U if not pre-wired
Villager	1997-1998	FRDF-AUX	16-Pin connector at headunit	Radio Series 165
Villager *	1999-2002	FRDN-AUX	20-Pin connector at headunit	Radio Series 868 or 870
Note 1: *If the 2001-2002 Villager is equipped with factory video system, use PIE Part # FRDW-AUX. (Factory pre-wire found in lower back section of radio dash console) Note 2: Not compatible with 2003 models equipped with 6-disc in-dash headunit or factory navigation system.				




DPX™ AUXILIARY INPUT CONVERTER

APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.
 ***FOR SATELLITE RADIO INTEGRATION, SEE BACK PAGE

MAKE/MODEL	YEAR(S)	PIE PART #	LOCATION	NOTES
MINI				
All Models	2002-2004	BMW/PC-SON	3 & 6-Pin connectors in trunk	Vehicles without DSP ONLY
Note: The BMW/PC-SON can be used as a CD-Changer or Auxiliary input interface.				
NISSAN				
Quest	1997-1998	FRDF-AUX	16-Pin connector at headunit	Must be CD changer controller headunit.
Quest	1999-2002	FRDN-AUX	20-Pin connector at headunit	Must be CD changer controller headunit.
Note 1: If the 2002 Quest is equipped with factory video system, use PIE Part # FRDW-AUX. (Factory pre-wire found in lower back section of radio dash console)				
Note 2: Not compatible with 2003 Quest.				
OLDSMOBILE				
Achieva *	1996-1998	GM10-AUX	Trunk	Not compatible with 2001-2004 Alero. Not compatible with 2000-2004 Aurora.
Alero *	1999-2000	GM10-AUX	Trunk	
Aurora *	1995-1999	GM10-AUX	Trunk	
Cutlass *	1997-1999	GM10-AUX	Trunk	
Cutlass Supreme *	1995-1997	GM10-AUX	Trunk	
Eighty-Eight *	1996-1999	GM10-AUX	Trunk	
Intrigue *	1998-2001	GM10-AUX	Trunk	
LSS *	1996-1999	GM10-AUX	Trunk	
Regency *	1997-1998	GM10-AUX	Trunk	
Silhouette **	1996-1999	GM9-AUX	Headunit	
Note 1: * Vehicle requires GM factory CD data cable, Part # 12344003, if not pre-wired.				
Note 2: ** Radio must be AM/FM/Cassette with 'TAPE/AUX' button.				
PLYMOUTH				
All Models	1995-2000	CHRY-AUX	Headunit	
Note: Radio must be one of the following CD changer controller headunits:				
<ul style="list-style-type: none"> • 5-preset radio with 5-band EQ, "DISC ^" and "DISC v" on presets 1 and 5, and "MODE" button. • 6-preset radio with Bass and Treble slider controls, "DIRECT DISC SELECT 1-6" printed above radio presets, and "MODE/EJECT" button. 				
PONTIAC				
Aztec	2002-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Bonneville	1996-1999	GM9-AUX	Headunit	Not compatible with 2000-2004 Bonneville
Firebird	1996-2002	GM9-AUX	Headunit	
Grand Am	1996-2000	GM9-AUX	Headunit	Not compatible with 2001-2004 Grand Am
Grand Am	2002-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Grand Prix	1996-2003	GM9-AUX	Headunit	Not compatible with 2004 Grand Prix
Grand Prix	2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Montana	1999	GM9-AUX	Headunit	Not compatible with 2000-2004 Montana
Montana	2002-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Sunfire	1996-1999	GM9-AUX	Headunit	Not compatible with 2000-2004 Sunfire
Sunfire	2002-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
TransSport	1996-1998	GM9-AUX	Headunit	
Vibe	2002-2003			Not compatible with 2003-2004 Vibe
Vibe	2003-2004	GM12-AUX	12-Pin connector at headunit	Must have XM-Satellite/RDS ready headunit.
Note 1: PIE Part # GM10-AUX can be used if vehicle is pre-wired with 10-position GM factory data cable.				
Note 2: AM/FM/SINGLE CD headunits use 9-Pin data port for an OEM cassette deck and are not intended for use with a CD changer.				
Note 3: Not compatible with vehicles equipped with in-dash 6-disc slave units.				
Note 4: GM radios 2000 and earlier are not capable of controlling two units; therefore, these radios will need to have the slave unit disconnected.				



DPX™ AUXILIARY INPUT CONVERTER APPLICATION GUIDE

PIE Auxiliary Input Converters allow you to convert the CD changer port of your OEM radio into auxiliary input. Auxiliary devices such as Mobile Video Systems, MP3 and Digital Satellite Radio can be added to the OEM radio WITHOUT FM MODULATION, resulting in optimum sound quality.
***FOR SATELLITE RADIO INTEGRATION, SEE BACK PAGE

MAKE/MODEL	YEAR(S)	PIE PART#	LOCATION	NOTES
SATURN				
All Models	1995-1999	GM10-AUX	Trunk	Not compatible with 2000-2004 Saturn
Note: Requires Saturn Part # 21023550 and Part # 21023253 if not pre-wired.				
SCION				
Xa	2003-2004	TOY-AUX	12-Pin data port at headunit	Requires Toyota Part# 08695-00370/PIE Part# TOY03-FMM Requires Toyota Part# 08695-00370/PIE Part# TOY03-FMM Requires Toyota Part# 08695-00370/PIE Part# TOY03-FMM
Xb	2003-2004	TOY-AUX	12-Pin data port at headunit	
All Models	2003-2004	TOY/PC-SON	12-Pin data port at headunit	
Note: The TOY/PC-SON can be used as a CD-Changer or Auxiliary input interface.				
TOYOTA				
All Models*	1998-2003	TOY-AUX	12-Pin data port at headunit	See Note 2: ** Requires Toyota part # 08695-00370 & PIE Part# TOY03-FMM See Note 2: **
Sienna	2004	TOY-AUX	12-Pin data port at headunit	
All Models	1998-2004	TOY/PC-SON	12-Pin data port at headunit	
Note 1: *Not compatible with 2003-Up Matrix, Prius and models equipped with navigation system. Note 2: ** 2003 models may require Toyota part # 08695-00370/PIE Part# TOY03-FMM if new (smaller, Approx. 3/4" wide) Toyota plugs are present. Note 3: The TOY/PC-SON can be used as a CD-Changer or Auxiliary input interface.				
VOLKSWAGEN				
All Models	1998-2004	VW-AUX	12-Pin data cable in trunk	
All Models	1998-2004	VWR-AUX	8-Pin data port at headunit	
Note 1: All vehicles listed above must be equipped with VW factory radio with round 'SCAN' Button. Note 2: VWR-AUX not compatible with 2002-2004 double-DIN AM/FM/CASS/CD radio and Navigation radios.				

FOR SATELLITE RADIO INSTALLATION WITHOUT FM MODULATION:

PIE Part# **PIO/P-RCA** converts the Pioneer XM Satellite receiver (GEX-FM903XM) audio signal (P-Bus) into RCA to allow connection with PIE Auxiliary Input Converters. In addition PIE Part# PIO/P-RCA will convert the CD Changer port of Pioneer Headunits (P-BUS) into an Auxiliary-RCA-input.

PIE Part# **3.5-RCA6MM** converts the Sony XM Satellite receiver (DRN-XM01R, DRN-XM01C) audio signal (3.5MM) into RCA to allow connection with PIE Auxiliary Input Converters.

Contact PIE Technical Support if you have questions concerning compatibility.